

Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

### FLAMMABILITY TEST REPORT

| Report No.: LEI22051475A        | Date Received: 13/05/22                      | Date Tested: 19/05/22 | Date Issued: 19/05/22 |  |  |
|---------------------------------|--|-----------------------|-----------------------|--|--|
| Company Name & Address:         | BEST PUR POLYMERS SP. Z O.O. SP.K.           |                       |                       |  |  |
|                                 | KRAZKOWY 51E                                 |                       |                       |  |  |
|                                 | 63-600 KEPNO                                 |                       |                       |  |  |
| Contact Name:                   | ANNA BICZYSKO                                |                       |                       |  |  |
| Sample Details                  |  |                       |                       |  |  |
| Reference No.:                  | Not stated                                   |                       |                       |  |  |
| Order No.:                      | Not stated                                   |                       |                       |  |  |
| Style. / Batch No.:             | Polyurethane foam CT-2840 / 20220426/CT-2840 |                       |                       |  |  |
| Quality:                        | Not stated                                   |                       |                       |  |  |
| Colour No.:                     | White  |                       |                       |  |  |
| Manufacturer:                   | BEST PUR Polymers Sp. zc                     | o.o. Sp.k.            |                       |  |  |
| Supplier:                       | BEST PUR Polymers Sp. zo                     | -                     |                       |  |  |
| Buyer / Retailer:               | Not stated                                   | -                     |                       |  |  |
| Intended Use:                   | Furniture and mattresses                     |                       |                       |  |  |
| Fibre Composition:              | Not applicable                               |                       |                       |  |  |
| Flame Retardant treated Fabric: | No   |                       |                       |  |  |
| Sample Description:             | White coloured polyurethan                   | e foam                |                       |  |  |

| Test Method   | Pre Treatment | Flammability Performance Requirements  | Result   |
|---|---------------|--|----------|
| BS 5852: Part 2: 1982,<br>Ignition source 5 (Crib 5) as<br>modified by Schedule 1 Part 1<br>of the Furniture & Furnishings<br>(Fire) (Safety) Regulations<br>1988 (As Amended). | None          | As Schedule 1 Part 1<br>(Ignition test for polyurethane foam in slab<br>or cushion form) of<br>The Furniture and Furnishings (fire) (safety)<br>Regulations 1988 (as amended). | Complies |

ANDREW HALLETT

(Flammability Team Leader)

STEVEN OWEN (Technical & Operational Excellence Manager)

Report No.: LEI22051475A Page 1 of 3

CAROLE SPOWART (Flammability Administrator)

GREGORY JAMES (Flammability Technician)

.....





Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

# FLAMMABILITY TEST REPORT

| <b>Filling Specification</b> |   |  |  |
|------------------------------|---|--|--|
| Filling Type:                | Polyurethane Foam   |  |  |
| Density / Hardness:          | Not stated / Not stated   |  |  |
| Cover Fabric:                | Standard test fabric as detailed in Schedule 1 Part 1 of The Furniture (Fire) (Safety) Regulations 1988 (as amended).   |  |  |
| Uncertainty of Measurem      |   |  |  |
| The uncertainty of meas      | urement has been estimated to be 5.99%  |  |  |
| Conditioning                 |   |  |  |
| Prior to Testing:            | At least 72 hours in ambient indoor conditions, then at least 16 hours in an atmosphere having a temperature of $20+5\%$ and a relative humidity of $50+20\%$ |  |  |

At Time of Testing:

a temperature of  $20\pm5^{\circ}$ C and a relative humidity of  $50\pm20\%$ Temperature between  $15^{\circ}$ C &  $30^{\circ}$ C. Relative humidity between 20% & 70%

### Test Results

"The following test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test; they are not intended as a means of assessing the fully potential fire hazard of the materials in use."

| Pass / Fail Criteria   | Initial test   |  | Repeat test  |  |  |
|--|--|--|--|--|--|
| Progressive smouldering failure  |  |  |  |  |  |
| Externally detectable amounts of smoke, heat or glowing 60 min after crib ignition                     | No   |  | No   |  |  |
| Escalating smouldering behaviour rendered the test unsafe to continue and required forcible extinction | No   |  | No   |  |  |
| Smouldering essentially consumed the test specimen within the duration of the test                     | No   |  | No   |  |  |
| Flaming failure  |  |  |  |  |  |
| The test specimen continued to flame for more than 10 minutes after the ignition of the crib           | No   |  | No   |  |  |
| Escalating combustion behaviour rendered the test unsafe to continue and required forcible extinction  | No   |  | No   |  |  |
| Flaming essentially consumed the test specimen within the duration of the test                         | No   |  | No   |  |  |
| Final examination  |  |  |  |  |  |
| Progressive smouldering was observed when the sample was dismantled                                    | No   |  | No   |  |  |
| Comments   |  |  |  |  |  |
| Time to extinction of flames after crib ignition   | 2 Minutes 56 Seconds   |  | 3 Minute 01 Second   |  |  |
| Time to extinction of glowing after crib ignition  | within the test s<br>not possible  | Due to the position of the crib<br>within the test specimen it was<br>not possible to see when<br>glowing ceased |  | Due to the position of the<br>crib within the test specimen<br>it was not possible to see<br>when glowing ceased |  |
| Time to extinction of smoke after crib ignition  | Due to the amount of smoke in<br>the test enclosure it was<br>not possible to see when<br>smoking ceased |  | Due to the amount of smoke<br>in the test enclosure it was<br>not possible to see when<br>smoking ceased |  |  |
| Maximum extent of damage to back (mm) Length / Width   | 400  | 160  | 400  | 120  |  |
| Maximum extent of damage to base (mm) Length / Width   | 105  | 160  | 116  | 156  |  |
| The resultant mass loss exceeded 60g   | No (26g)   |  | No (27g)   |  |  |
| Test Result  | PASS   |  | PASS   |  |  |

#### **Conclusions**

The sample tested meets the requirements of Schedule 1 Part 1 (Ignition test for polyurethane foam in slab or cushion form) of The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended). **PASS**.



Report No.: LEI22051475A Page 2 of 3



Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

## FLAMMABILITY TEST REPORT

The client acknowledges and agrees that any services provided and/or reports produced by Intertek are done so within the limits of the scope of work agreed pursuant to the client's specific instructions. This report relates specifically to the sample(s) tested that were drawn and delivered by the client or their nominated third party. Intertek does not make any representation or warranty for any bulk samples or certify the bulk samples received from the client. Furthermore, Intertek does not provide a warranty or verification on the sample(s) representing any specific goods, material and/or shipment and only relate to the sample(s) as received and tested. Intertek have aimed to conduct the review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. In no event, will the contents of any reports or any extracts, excerpts or parts of any reports be distributed or published without the prior written consent of Intertek in each instance. Only the client is authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.

The reported expanded uncertainty is based on a standard uncertainty multiplied by a coverage factor of k = 2, providing a level of confidence of approximately 95 %. Unless otherwise specified all compliance and pass/fail statements are binary simple acceptance based on the tolerance interval and, with the exception of graded methods, a test uncertainty ratio greater (TUR) than 4:1. For graded methods the TUR will drop to as low as 0.5:1 when the tolerance limits are within a grade division of the upper scale limit. The Uncertainty budgets are stated for each Test method, these are for reference, and should be considered when results are on or close to Specification Limits / Requirements and in such cases it should be noted that the risk of false acceptance or rejection may be as high as 50%, for further information please refer to ILAC G8.



Report No.: LEI22051475A Page 3 of 3